Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

 LG1545
 BACKYARD & BASEMENT
 NY Spills
 S112231011

 ENE
 2669 EAST 26TH ST
 N/A

> 1 1.948 mi.

10287 ft. Site 1 of 2 in cluster LG

SHEEPSHEAD BAY, NY

 Relative:
 SPILLS:

 Higher
 Name:
 BACKYARD & BASEMENT

 Actual:
 Address:
 2669 EAST 26TH ST

 10 ft.
 City,State,Zip:
 SHEEPSHEAD BAY, NY

 Spill Number/Closed Date:
 1211071 / 2012-11-17

Facility ID: 1211071 Facility Type: ER DER Facility ID: 429475 Site ID: 474207 DEC Region: 2 Spill Cause: Storm Spill Class: C4 2401 SWIS: Spill Date: 2012-10-29

Investigator: Hurricane Sandy R2
Referred To: Not reported
Reported to Dept: 2012-11-16
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling

Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: Not reported
Remediation Phase: 1

Date Entered In Computer: 2012-11-16
Spill Record Last Update: 2012-11-16
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: Not reported
Spiller Company: Not reported
Contact Name: YELENA SIWINSKI

DEC Memo: "This spill report was created for tracking purposes related to the Department's Hurricane Sandy emergency response efforts. DEC

contractor Op-Tech pumped out 70 gallons of fuel oil on 11/17/2012"

Remarks: "Needs tank pump out (in basement) Also has 3-4 10 gal containers of

oil/water mix on back steps"

All Materials:

Site ID: 474207 Operable Unit ID: 1224047 Operable Unit: 01 Material ID: 2222218 Material Code: 0001A Material Name: #2 fuel oil Case No .: Not reported Material FA: Petroleum Quantity: 100.00 Units: G Recovered: 70.00 Oxygenate: Not reported